## In the Specification:

On page 5, line 28: Please replace lines 28-36 with the following rewrite:

81

--In a preferred form, two flexible internal barriers 24 are used, one on each side of the entry frame 22 leading into the socket cavity. A flexible internal barrier 24 is composed of a flexible ramp 26 having a fixed end 27 and a movable end 29. The fixed end 27 is fixedly attached at the entry frame 22. The movable end 29 extends into the socket cavity. Attached to the movable end 29 is a vertical barrier 28, which moves with the movable end 29 of the flexible ramp 26. When the flexible ramp 26 is not flexed, the vertical barrier 28 remains in a central stopping position within the cavity which would prevent a plug from moving past it further into the socket cavity.--

On page 6, lines 1-9: Please replace lines 1-9 with the following rewrite:



--Figure 3 provides a side view of the doorway or entry frame 22 for an improved socket connector having a flexible internal barrier 24 to prevent incorrect insertion of smaller sized plugs in accordance with this invention. In Figure 3, a plug 11 is shown inserted. The plug 11 engages the flexible ramp 24 which forces the movable end 29 and vertical barrier 28 downward out of the central stopping position previously shown. When the vertical barrier 28 is moved downward out of the central stopping position previously shown, the plug 11 can be moved past it further into the socket cavity.--

On page 6, line 11, please add a comma (,) after "frame 22".

P2341